

## REPLACEMENT SHEET

3/11




Fig 4




Fig 5





Fig 6

REPLACEMENT SHEET

5/11






Fig 8

# REPLACEMENT SHEET

7/11

90

Maintenance Log for Test sensor

Log:

2003-04-16 11:02: Sensor installed by Henrik Larne


Time: 2003-04-16 11:02

Entry: Sensor installed by Henrik Larne

92

New Entry Save Log Close

**Fig 9**

**Fig 10**

# REPLACEMENT SHEET

9/11




Fig 11

# REPLACEMENT SHEET

10/11




Fig 12